DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-010280

Address: 333 Burma Road **Date Inspected:** 27-Oct-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Shanghai, China

CWI Name: Yes Gong Ling Zhu, An Qin Xiang. **CWI Present:** No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes N/A **Delayed / Cancelled:** No

> **Component:** Tower Components

Summary of Items Observed:

Bridge No:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Amit K. Juvekar, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 11, West tower, Lift 1 & 2.

1) Installing Interior Splice Plate On skin B.

34-0006

2) AB/F carried out Magnetic Particle Testing (MT) Inside.

Bay 11, West tower, Lift 1 & 2.

- 1) Preparing for Installation of Interior Splice Plate On skin E.
- 2) AB/F carried out Magnetic Particle Testing (MT) Inside.

Bay10, South Tower, Interior Splice Plate Repair.

FCAW Repair welding of weld joint SSD1-SPSA3-56-3A(WRR # T-WR2527); located on Bay10, South Tower. Welders are identified as 062782; ZPMC Quality Control Inspector (QC) is identified as Gong Ling Zhu. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-345-FCAW-1G(1F)-Repair.

Bay11, West Tower, Lift 4, BC & AB Corner Seam Ring Area.

SMAW welding of weld joint WSTL4-2B/L-58A, 59A; located on Bay11, West Tower, Lift 4, BC & AB Corner Seam Ring Area. Welders are identified as 040611, 202323; ZPMC Quality Control Inspector (QC) is

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

identified as An Qin Xiang. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: 1) WPS-B-P-214-C-U2, 2) WPS-B-P-214-B-U2.

Bay 11, West Tower, Lift 2.

During Ramdom in Process inspection this QA Inspector observed ZPMC cutting out B/C corner Diagonal Stiffener. The attached photographs provide additional detail.

This QA Inspector carried out NDE on following

Bay 10, East Tower, Web Plate of Struts.

This QA inspector performs Random Magnetic Particle Testing (MT) of approximately 15% area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report (TL-6028) for this date. The members are identified as

- 1) ED1-STSA3-2-89M-1-1, 2, 4, 6.
- 2) ED1-STSA3-2-89M-2-1, 2, 4, 6.
- 3) ED1-STSA3-2-99M-1-1, 2, 4, 6.
- 4) ED1-STSA3-2-99M-2-1, 2, 4, 6.
- 5) ED1-STSA3-2-109M-1-1, 2, 4, 6.
- 6) ED1-STSA3-2-109M-2-1, 2, 4, 6.


Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





WELDING INSPECTION REPORT

(Continued Page 3 of 3)









Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod, 13482570045, who represents the Office of Structural Materials for your project.

Inspected By:	Juvekar, Amit	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer